

QTY	DESCRIPTION	UNIT	PRICE	TOTAL	REMARKS
1	ETB Battery 136-903-9001		46.90	46.90	
1	Washerfield		16.90	16.90	
1	Rocker Box Cover		2.22	2.22	
4	Rocker Air Bushings 69612		30.00	120.00	
1	Cylinder w/ component parts		247.29	247.29	
1	74636 Rocker Arm		13.55	13.55	
1	452573 Belt		4.48	4.48	
1	452572 Belt		3.28	3.28	
1	GS 35 Clamp		80.00	80.00	
2	10-720512-65 Reattachment Ids		15.35	30.70	
2	MS21919		60.00	120.00	
	TOTAL PARTS		621.66	621.66	
	OUTSIDE REPAIRS				
	LABOR 52.02 Hours @ \$ 11.00 ea.				
	TOTAL			728.98	
	TOTAL PARTS			521.66	
	OUTSIDE REPAIRS				
	TOTAL			20.97	
	TOTAL			270.61	

1	Plug for right wire also missing.
1	Carry over.
2	Battery low on charge.
2	Charged battery to full charge.
2	Both windshield cracked.
3	Washerfield removed. Part ordered 10-1-78.
4	ETB Battery ordered.
4	Replaced battery.
5	Right front seat will not pull forward.
5	No defect found.
6	Left rear seat back is off. 6. Installed rear seat back.

QTY	DESCRIPTION	UNIT	PRICE	TOTAL
	OT. OIL			
	SOVENT			
	TOTAL			
	OUTSIDE REPAIRS			
	TOTAL			
	FREIGHT			



RYAN C. BELL
 323 ROBERT B. B. NEVILLE, JR.
 GREENVILLE, S.C. 29608
 (803) 242-3328 (803) 242-3333
 Customer # 33479 03030

RECORDED AUG 15 1978

4978