

MOTORS AND TABLES

<u>MAKE</u>	<u>H.P.</u>	<u>R.P.M.</u>	<u>SERIAL</u>	<u>TABLE</u>
Singer	1/2	3500	M616267	4'
"	1/2	3500	M597650	4'
"	1/2	3500	M617085	4'
"	1/2	3500	M616787	4'
"	1/2	3500	M616206	4'
"	1/2	3500	M618975	4'
"	1/2	3500	M624678	4'
"	1/2	3500	M598659	4'
"	1/2	3500	M534924	4'
"	1/2	3500	M535093	4'
"	1/2	3500	M561724	4'
"	1/2	3500	M565141	3-1/2'
"	1/2	3450	M601265	3-1/2'
"	1/2	3450	M601180	3-1/2'
"	1/2	3500	M624581	4'
"	1/2	3500	M616829	4'
"	1/2	3400	M470910	3-1/2'
"	1/2	3500	M597144	3-1/2'
"	1/2	3500	M597158	3-1/2'
"	1/3	3400	M458968	3-1/2'
"	1/3	3400	M459715	3-1/2'
"	1/2	3400	M565051	3-1/2'
"	1/3	3400	M545673	3-1/2'
"	1/3	3400	M543457	3-1/2'
"	1/3	3400	M458873	3-1/2'
"	1/3	1725	M325682	3-1/2'
"	1/3	"	M499516	3 1/2 x 2 1/2'
"	1/3	"	M499475	" "
"	1/3	"	M593550	- -
"	1/3	"	M593289	4'
"	1/2	3500	M546210	3-1/2'
"	1/2	3450	M600305	3-1/2'
"	1/2	"	M600307	3-1/2'
"	1/3	3400	M458871	3-1/2'
"	1/3	"	M458950	" "
"	1/3	"	M458429	" "
"	1/2	3450	M600314	" "
"	1/2	3450	M601266	" "
"	1/2	"	M600163	" "
"	1/2	"	M600256	" "
"	1/3	1725	M556481	5 1/2 x 25"
"	1/3	"	M566418	" "
"	1/3	"	M497700	4' x 21"
"	1/3	"	M514921	" "
"	1/3	3400	M438421	3-1/2'