



Sir immediately after I recd your letter I attended  
 on the above described land and I began  
 the resurvey on the large Bo. 3+ on the old line &  
 run due N 75° to the Post now down then S 20°  
 W 73 but found no markers nor State Corner the  
 State 3+ that Mr Nations showed to you near his  
 fence I found was made by him, when he surveyed  
 the land thence N 55° W 82.50 But found no markers  
 nor corners to answer then I came back to the begining  
 oak & run S 55° W 76.50 found both the stations and  
 corn to a tree thence N 40° W 82.50 - 87.50 Bo. 3+ that  
 appears to have been made for this land looks like  
 then runs N 20° W but could find no stations  
 nor corners to answer neither is the Platt laid