

STATEMENT BOOK 16 PAGE 1166
FROM Robert B. Jones

December 15, 1974

TO Windmere

ADDRESS

CITY STATE

TERMS

Apt #105 Repair heat unit	20.00
Apt #305 Replace door bell	10.00
Apt #106 Repair dishwasher	25.00
Apt #101 Repair stove broiler	
Wiring left out at factory	20.00
Apt #105 Repair heat-split	
bolts not installed	25.00
Apt 906 Repair heat-split bolts	
not installed	28.00
Apt 104 Repair heat unit -	
compressor to be replaced	
by Barnett	
Repair oven	50.00
Clubhouse - Repair gas dryer	18.00

CRAYON FOR SIGN

USA

PRINT

4328 RV-2J