Plat Book 00, Page 257.

W N WILLIS HEMBERS C SOCIETY OF ENGINEERS

YOUNTS & SPENCE WAY .

KATABLIBHED IBIO

W. N. WILLIS

CIVIL AND CONSULTING ENGINEERS

POMER AND PROPERTY DEVELO

SPARTANBURG, S.C.

CORRECTION OF LOT LINES ON PLAT OF B. F. FLYNN ESTATE RECORDED IN FLAT BOOK B PAGE 81.

About the time W. 7. Bidwell purchased this property (1955) I checked by measurements and found nearly all, if not all, the corners designated of lots from 1 through 15 marked with iron pins, and during grading and construction of the building, the iron pins between lots 10 and 11 were specially noted. These points were marked with iron pins when Dr. Bidwell purchased same. Though I did not check the angle.

On March 30, 1959 with Mr. E. C. Allen from office of Dalton and Neves Engrs. cffice, with Dr. Bidwell and Mr. Collins present, we checked from old iron pin, corner of Lot No. 1 (a), fence corner (b) old iron pin at (c) to iron pin between lots 10 and 11 (d) iron pin between lots 16 and 17 (e), through lot No. 20 with lot No. 21 marked 116 feet, more or less.

Mr. Allen with Dalton and Neves, Engrs. turned the 90 degree angle from the iron pin at rear as shown on plat and the point came three (3) feet to the left on Dr. Bidwell's side of the old iron pin corner between lots 10 and 11. This shows an error was made in the plat - B. F. Flynn's Estate- Plat No. 1 as recorded in Plat Book B page 81. This revision is on the plat by H. S. Brockman, Surveyor, May 9, 1947, Subdivided April 3C, 1947 and this note added "Note this subdivision changed slightly from Brockman survey - Plat revised and redrawn, lots renumbered June 25, 1947 by H. L. Dünahoo, Surveyor, Winder, Georgia.

Sworn to before me this /st.

day of April ,A.D.1959

Mattie Sue Sutman (SEAL)
Notary Public for S. C.

W. N. Willis, Engineers

Spartanburg, South Carolina