·134471 - S. 4. Holland Koem L—2. THE FEDERAL LAND BANK OF COLUMBIA. TRACING SHEET FOR PLATS. Lands of I This sheet must be used for tracing blats of tracts of the lands abstracted in the chain of title. Place this sheet over the plat to be traced so that the same will appear as nearly in the center, of the sheet as possible; then trace all lines, courses and distances. Always show all adjoining landowners and indicate the point of the compass and copy all legands or explanatory notes, showing the date of survey, purpose of the same and by whom made.

24t the plat is too large to be traced on this pheet, make the tracing first on Sheet Q.1, and then reduce it on Sheet Q in the following manner: Assume that a certain corder on the tracing of Sheet Q.1 lies within Block 14-C. Refer to Sheet Q and locate this corner in corresponding Block 16-D. The next corner on Sheet Q.1 sheet within Block 14-C. Refer to Sheet Q.1, and locate this corner in the corresponding Block 16-D and locate this corner in the corresponding Block 16-D and locate this corner in the corresponding Block 16-D and locate the corner on Sheet Q.1, locating the corresponding corners on Sheet Q.1 are connected. So proceed around the perimeter of the plat of land as traced on Sheet Q.1, locating the corresponding corners on Sheet Q.1 and connecting the various corners so located until the point of departure is greated in the fabstract at its proper page, which is immediately following the instrument or proceedings which refers to the plat of which this is a copy. 13 16 رماا 00.1 3花成了 20 TO TON The state of the s 248 store Scata Cart Greenville By request of Victor Smith,
Thave surveyed in part, and
plated the above tract of land,
situated in Austin Township, State
and County aforesaid, containing
sixty live acros, and hath such
shares marks and hourds and 33 93 shares, marks, and bounds as shown July 19th, 1917.
W. A. Adams, Surveyor. Sheet Q