

P.O. BOX 212
FORT MYERS, FLORIDA 33902

BILL DANIELS & ASSOCIATES
MARINE SURVEYORS

BOOK 8 PAGE 147

January 19, 1973

Vessel: BARRACUDA

Survey # 173C106

This is to certify that the undersigned surveyors proceeded to Fort Myers Beach, Florida on the above date and surveyed the above vessel afloat. Present was one of the owners, Walter F. Kuntz and wife.

Found the vessel to be in good, sound, seaworthy condition, all machinery also. We found the above to be subject to the following recommendations:

1. Harness primary wiring in engine compartment and locker.
2. Replace with new, damaged wood grating over Port, starboard, Fuel tanks.
3. Clean, inspect and recoat tops of the port and starboard fuel tanks.
4. Install intake and exhaust air vents to engine compartment.
5. Remove sea cock in engine compartment or plug off from bottom side.
6. Check and certify five existing fire extinguishers.
7. Vessel should be hauled in near future for cleaning of bottom and recoating with antifouling paint.


The vessel is equipped with three electric fishing reels, fish boxes holding approximately 5500 pounds, and bait box, the latter two are fiber glass lined.

The vessel was last hauled on September 11, 1973 by Desco boat yard and condition was reported good.

The owner stated that he would comply with the progoing recommendations and when this is accomplished we place the value of the vessel at approximately \$12,000.00.

Signed without prejudice,


Bill Daniels


Lynn Gerald

Attending Surveyors

ED/LG:wc

Enclosure: Two color photos

Attending Surveyor

Bill Daniels and Associates Organization, or its representatives, agents or employees, are not to be held responsible for any inaccuracy, omission, misstatement or error in judgment. To all intent, purpose and interest, reports emanating from this office may be judged as an evaluated opinion of the attending surveyor.

RECORDED NOV 28 '73

14017

4328 (W-2)