

## UNDERGROUND WORK -

SPREAD STONE IN BASEMENT	140. <sup>00</sup>
1" WATER TAP	275. <sup>00</sup>
1" WATER SERVICE TO HOUSE	456. <sup>00</sup>
4" SEWER TO HOUSE.	1155. <sup>00</sup>
REPAIR WATER PIPE DAMAGED BY GRAD.	280. <sup>00</sup>
INSTALL 24" PIPE @ DUNE	215. <sup>00</sup>
DOWNSPOTS 200' @ 3.50	700. <sup>00</sup>
80' @ 4.00	320. <sup>00</sup>
6 DOWNSPOTS @ 15. <sup>00</sup>	90. <sup>00</sup>
AIR COMPRESSOR TO REMOVE ROCK	140. <sup>00</sup>

TOTAL OUTSIDE & BACKHRE WORK	3771. <sup>00</sup>
------------------------------	---------------------

TOTAL BALANCE FOR WORK DONE  
IN HOUSE TO DATE. - 80% COMPLETE,  
UNDERGROUND & CHANGES

COLLECTED TO DATE

12,095. <sup>56</sup>
800. <sup>00</sup>
5,000. <sup>00</sup>
<u>1,500.<sup>00</sup></u>
7,300. <sup>00</sup>