



PROPERTY OF
JOHN MARK McCLAIN
 AND
JANE W. McCLAIN
 NEAR PIEDMONT, GREENVILLE COUNTY, S.C.
 SCALE 1" = 50' JULY 6, 1977

1238

FILED
 GREENVILLE CO. S.C.
 JUL 12 12 10 PM '77
 DONNIE S. TANKERSLEY
 R.M.C.

This is to certify that on July 6, 1977, I surveyed the property shown on this plat, known as Property of John Mark McClain and Jane W. McClain as shown on a plat recorded in the RMC Office for Greenville Co. in Plat Book _____ at page _____, and that the property lines, walls and building are as shown hereon, and that the building located on said lot does not project nor encroach on adjacent streets or property, and that no adjacent walls or buildings project nor encroach on said lot, and that no utility lines cross this lot except as may be shown hereon.

NOTE: This property is not located within a flood hazard area.

Survey by Richard Wooten Land Surveying

Richard Wooten
 S. C. R. L. S. No. 4678

871200012A

1.000A1